


# SPECIAL AIRWORTHINESS INFORMATION BULLETIN

Aircraft Certification Service  
Washington, DC



U.S. Department  
of Transportation

**Federal Aviation  
Administration**

No. CE-04-30  
December 9, 2003

*www.faa.gov - Search "SAIBs"*

*This is information only. Recommendations aren't mandatory.*

---

## Introduction

This Special Airworthiness Information Bulletin informs you, owners and operators of **BAE Systems Jetstream 3200 series aircraft**, that BAE Systems has issued a *mandatory* service bulletin (SB) 57-JA021140, for an inspection of the wing lower skin at inboard end of auxiliary spar boom and main landing gear cut doubler between wing stations 64 and 70.

## Background

BAE Systems conducted fatigue testing and found it necessary to introduce the inspection described in SB 57-JA021140.

## Recommendation

We aren't issuing an AD at this time, but highly recommend that you accomplish the inspections stated in the SB.

## For Further Information Contact

Taylor Martin, Aerospace Engineer, FAA Small Airplane Directorate, ACE 112, 901 Locust, Room 301, Kansas City, MO 64106; phone: (816) 329-4138; fax: (816) 329-4090; email: [taylor.martin@faa.gov](mailto:taylor.martin@faa.gov)

For copies of the service bulletin, contact BAE Systems, Prestwick International Airport, Ayrshire, KA9 2RW, Scotland; phone: +44 (0) 1292 479888; fax: +44 (0) 1292 479703.